

State of UtahDEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

Report Date June 29, 2005

Supervisor Lond

Weather: Partly cloudy, 70's

| Mine Name: Bacon Rock | Permit number: S/037/101 |
|------------------------------|---------------------------------------|
| Operator Name: Bedrock Stone | Inspection Date: June 10, 2005 |
| | Time: 10:30 to 11:00 AM |
| Inspector(s): Paul Baker | |
| Other Participants: None | |

Elements of Inspection Evaluated Comment Enforcement 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other

Purpose of Inspection:

Mine Status: Reclaimed

I anticipate the operator requesting a closure inspection, and since I was in the area, I decided to stop and see if I felt the site would meet release criteria.

Inspection Summary:

10. Revegetation

With good precipitation for about the last year, vegetation has progressed very well. This is the third growing season since the site was seeded.

I took measurements of perennial vegetation cover in disturbed and undisturbed areas. There were 21 samples in the disturbed area and 11 in the undisturbed area. The measurements I obtained were 20.7 percent cover in the reclaimed area and 11.2 percent in the undisturbed area.

Photos 1 through 4 show the revegetation. It is very dense in places with little growing in others, but the overall success is very good. The surface is rocky, and I saw no signs of erosion.



Inspection Date: June 10, 2005; Report Date: June 29, 2005

Page 2 of 2 S/037/101

Conclusions and Recommendations:

When the operator requests that this site be released, no further inspection should be needed. As far as I can determine, the site meets release criteria.

Inspector's Signature

Date: June 29, 2005

PBB:jb

cc:

Eldon Virgil, Operator

Ted McDougall, Monticello BLM

Attachment: Photos

O:\M037-SanJuan\S0370101-BaconRock\inspections\ins-06102005.doc

ATTACHMENT

Photographs S/037/101, Bacon Rock Quarry, Bedrock Stone

Inspection Dated: June 10, 2005; Report Dated: June 29, 2005



Photo 1. One of the more lush areas.



Photo 2. This is more typical of the vegetation cover.



Photo 3. The eastern edge of the disturbance.




Photo 4. There are some bare areas.